



November 27, 2019

NOTICE TO ALL REGISTERED ACCOUNT HOLDERS

Re: GM Forward Facing Camera Calibration

GM is changing several of their forward facing camera calibration documents in order to align with their upcoming Advanced Driver Assistance Systems (ADAS) calibration position statement. At this time, there is no scheduled date of release for the GM ADAS calibration position statement.

In the interest of proper repair, MPI recommends that repair shops research and follow the most current OEM repair information for calibration requirements and procedures.

Previously, GM's forward facing camera module calibration procedures led to confusion regarding self-calibration. To clarify, MPI defines "self-calibration" as any calibration process that does **not** require:

- A scan tool
- Physical targets
- Specialized equipment or training

With rapid changes in vehicle technology, MPI will continue to support the Manitoba repair trade. If you have any questions about this notice, please contact Estimatix using the [Repair Shop Support Line](#).

For further information about MPI's rules for calibration, refer to the [Advanced Driver Assistance Systems \(ADAS\) Calibration Estimating Standard](#).